

Service Slants

Acura

MIL on, VPS code(s) logged.

Some 2013 2WD RDX trucks built from VINs 5J8TB3...DL000001 through 5J8TB3...DL006466, as well as 4WD models built from VINs 5J8TB4...DL000001 through 5J8TB4...DL009205, may intermittently illuminate the MIL and log Valve Pause System (VPS) codes P3400 and/or P3497 in the PCM. One probable cause of the trouble, reports Acura, is a sticking rocker arm oil pressure switch on one or both banks of the engine. Installing a new-design pressure switch and O-ring (Part Nos. 37240-R70-A04 and 91319-PAA-A01, respectively) should eliminate further trouble.

Before ordering the new parts, however, check the engine oil dipstick, because a low oil level will definitely cause the VPS to go haywire and store the DTC(s) noted. If the oil level is low, add oil, clear the code(s) and release the vehicle to the customer. If the oil level is on the money or the truck comes back with the same complaint, go ahead and replace the front and/or rear pressure switch and O-ring, depending on the code(s) logged. The location of each rocker arm oil pressure switch and its respective DTC is shown in the accompanying illustration.

Ford Truck

Engine shudder, possible turbocharger noise with DTC logged.

Some 2011-12 F-250/350 Super Duty pickup trucks with the 6.7L diesel engine built on or before 5/16/12 may experience a shudder from the engine while being driven at steady throttle in the 900- to 1400-rpm range.

According to Ford, the engine shudder may be accompanied by a fluttering noise from the turbocharger and is more noticeable at higher elevations or ambient temperatures and/or when driving up a slight incline. On some vehicles, the MIL may be illuminated, with DTC P0299 logged in the




Illustration: Motor Magazine

PCM. Software issues in the module are the root cause of all of the woes.

Begin your diagnosis by hooking up a scanner and checking for trouble codes. If any DTCs other than P0299 are logged, this information doesn't apply; continue troubleshooting until the causes of the driveability woes are resolved. If no codes are stored or the only code logged is the P0299, reprogram the PCM with updated software. To do the flash, you'll need an IDS operating at software release 83.01 or higher. If you have a subscription, you can also download the new calibration files at www.motorcraft.com.

Dodge Truck

Cruise control troubles. Dodge reports that the cruise control systems on some 2011-13 Durango and Journey SUVs and 2013 Ram 1500-3500 pickup trucks may be slow to respond or may not activate at all when commanded by the switch.

According to the venerable truck manufacturer, the problem is limited to vehicles built on or before 5/1/13 and is due to software glitches in the Steering Column Control Module

(SCCM). Flashing the SCCM with updated software is the only sure-fire remedy. To do the flash, you'll need a wiTECH scanner operating at software release 14.02 or higher.

GM

Inoperative convertible top. The owner of a 2004-09 Cadillac XLR or 2005-10 Chevy Corvette may come in with a complaint that his convertible top won't go up or down. When he does, ask if the car battery was run down or disconnected for service. If the answer is yes, you can be sure the power window module has lost its initialization, and it's this module that the convertible top is dependent on for proper operation. Reinitializing the window module should get the top moving again.

To do the job, get into the car and make sure both doors are fully closed. Now turn on the ignition, push both window switches to the Up position and hold for five seconds. The window module should now be initialized and the convertible top should work. If it does, you're done with the fix. If not, repeat the initialization sequence.

Acura MIL illuminated, evap system DTC(s) stored. Acura reports that many of its 2011-13 vehicles may turn on the MIL and log evap DTC P0455 and/or P0456 in PCM memory. Before you plunge right into heavy diagnosis with your smoke machine, check the gas cap; it may be loose or have a stick-slip feel when tightened, which indicates an improper seal at the fuel pipe flange. The material that the cap gasket is made of is what's causing all the trouble.

Installing an updated gas cap with differently formulated gasket material is the simple fix. Order Part No. 17670-SZN-A01 for ZDX models and 17670-TRO-A11 for ILX, MDX, RDX, TL and TSX models.

Before ordering the new gas cap, however, remove the existing cap and take a look at the color of the gasket. If it's brown, the new cap is already installed and this information doesn't apply, and you should continue troubleshooting until the evap system leak is resolved. If the gasket is black, go ahead and install the updated gas cap with confidence.

Vehicles that are prone to the evap system leaks and can benefit from the updated gas cap are 2011-13 TSX models; 2012-13 MDX, RDX, TL and ZDX models; and 2013 ILX models.

Saab

Air bag light on, DTC stored. The owner of a 2006-07 9-7X model may come into your shop one day soon with an illuminated air bag warning light. When he does, immediately hook up your scan tool and check for trouble codes. If the only code you pull is DTC 023, chances are good the passenger-side seat belt tension sensor has gone *kaput*, reports Saab.

To make the diagnosis, check the wiring to the tension sensor for cuts, shorts or chafing. If everything looks okay, the sensor itself is most likely defective. Replacing the entire seat belt retractor (the tension sensor is

integral with the retractor and not available separately) should turn off the warning light immediately.

Pontiac Engine runs hot and/or inadequate heater output. Some 2007-

continued on page 46

Brilliant In Every Respect!

TRACERLINE® OPTI-PRO™ Plus

Leak Detection Flashlight

This super-compact, rechargeable leak detection flashlight features a high-output true UV (violet light) LED that causes dyes to fluoresce far more brilliantly and with greater contrast compared to conventional blue light lamps. Works with all universal/ester and PAG A/C dyes, as well as most popular fluid dyes. Provides 4 hours of continuous inspection between charges!





- Power comparable to high-intensity 125-watt lamps!
- Inspection range of 20 feet (6.1 m) or more!
- Convenient on-board recharging
- Powered by one rechargeable lithium-ion battery (included)
- Comes complete with smart AC charger, fluorescence-enhancing glasses and lanyard



Also available in the TP-8656 EZ-Shot™ OEM-Grade A/C Leak Detection Kit

Kit includes EZ-Shot™ caulking gun-style A/C dye injector, R-134a hose/coupler with purge fitting, 8 oz (237 ml) BigEZ™ R-134a/PAG multi-dose A/C dye cartridge, GLO-AWAY™ dye cleaner, smart AC charger, fluorescence-enhancing glasses and rugged carrying case.





TRACER PRODUCTS
A Division of Spectronics Corporation
956 Brush Hollow Road
Westbury, New York 11590 USA

To learn more, scan QR code,
call 1-800-641-1133
or visit www.tracerline.com

Circle #25

Service Slants

09 Solstice GXP models may illuminate the overheat warning lamp on the dash and/or suffer from insufficient heater output.

One likely cause of both maladies, reports GM, is air pockets in the cooling system. Installing a new check valve (Part No. 20876185) into the coolant return hoses at the engine and radiator should eliminate the troubles in short order.

To ease installation into the hoses, coat the valves with nonsilicone-based tire lubricant or antifreeze. When installed properly, the valves should be positioned vertically, with their tapered ends facing the nipples of the engine port and radiator.

Ford

Fluctuating idle with possible MIL illumination and stored DTC(s). Some 2005-07 Ford Five Hundred and Freestyle models, along with Mercury Montegos (all with the 3.0L engine and CVT transmission), may produce a fluctuating idle. According to Ford, the rpm fluctuation can be intermittent and may be accompanied by an illuminated MIL, with DTCs P061B, P0505 and/or P0506 stored in computer memory. Reprogramming the PCM with updated software and cleaning the throttle body and plate *may* eliminate the trouble.

To find out for sure, first flash the PCM with new calibration files using an IDS scanner operating at software release 74.03 or higher (if you have a subscription, you can also download the files at www.motorcraft.com). With the new software installed, shut the engine off, then restart it and allow it to idle until normal operating temperature is reached. Now run the engine at least 5 minutes more to allow the electronic throttle body compensation strategy to relearn.

When the relearn has successfully completed, check the value of PID ETC_TRIM in the datastream. If the value is less than 3° and DTC P115E is not present, but the idle fluctuation remains, cleaning the throttle body and plate won't do any good. Continue with normal troubleshooting until the problem is resolved. However, if the ETC_TRIM value is 3° or greater and/or DTC P115E is stored, the throttle plate and bore can definitely benefit from a good, old-fashioned scrubbing.

Start by removing the throttle body from the engine. Using Motorcraft Choke and Linkage Cleaner (Part No. PM-14) or an equivalent solvent, thoroughly spray the throttle plate and bore. Allow the cleaner to work, then scrub the edges of the plate and the mating surface of the bore with a stiff, solvent-resistant brush. When everything looks good and clean, give the plate and bore another shot of the cleaner and allow to air dry. To complete the fix, reinstall the throttle body, repeat the compensation strategy relearn and verify that the idle fluctuation issue has been resolved.

Saturn

SRS warning lamp illuminated, DTCs logged. Some 2005-07 Relay and 2008-10 VUE models may illuminate the SRS warning lamp on the dash and store DTC B0071 in the passenger presence system and DTC B0081 in the sensing and diagnostics module. One likely cause of the trouble, reports GM, is a defective front passenger seat belt tension sensor. Replacing the complete seat belt buckle (the tension sensor is part of the buckle assembly and can't be serviced separately) with an improved design should turn out the light. Check with a dealer for the buckle part number of the vehicle in your service bay.

Ford Truck

Squeaking noise from brake pedal. Ford reports that some 2013-14 Escape SUVs may produce an annoying squeaking sound whenever the brake pedal is depressed. One likely cause of the noise, says the carmaker, is the brake pedal's clevis pin binding against the brake booster pushrod. Installing a new-design clevis pin (Part No. 3M5Z-2L523-AA) and lubricating it with high-temperature wheel bearing grease should eliminate the irritation immediately.

Jeep

Poor ride or handling over rough roads. Some 2007-09 Compass and Patriot models built before 4/23/09 may ride roughly or handle poorly when driven over bumps and other rough road surfaces. One likely cause of the trouble, says

continued on page 48

ATEQ

VT56 MORE THAN JUST ANOTHER TPMS TOOL!

TPMS EASY AS 1-2-3

- Full Color 4" Screen
- Icon Driven Intuitive Learning
- Part Number Lookup
- OBDII Module for ECU Reset
- Dated History File
- Programs all Popular Programmable Sensors
- Vehicle DLC Locator
- Key Fob Tester
- RF Signal Tester
- Help Screens
- WiFi/Bluetooth Capability
- Barcode Scanner for Vehicles ID
- TPMS DTC Retriever
- US/European/Asian Vehicles
- Full Relearn Procedures

01 SCAN THE VIN

02 TRIGGER SENSORS

03 RELEARN TPMS

WWW.ATEQTPM.COM • 888-621-TPMS (8767)

Circle #26

Service Slants

Jeep, is a leaking front strut. The problem can occur on one or both sides of the vehicle. Replacing the strut(s) along with the jounce bumper and dust shield is the obvious fix. Be aware that the jounce bumper and shield are now two separate parts, replacing the one-piece design used in the past. Order Part No. 05171137AB for the new jounce bumper, 05171132AC for the new dust shield.

Scion

Front suspension noise. Scion reports that some 2008-12 xD models may produce a clunking sound from the front end when accelerating or decelerating, while braking or when being driven over rough or undulating roads.

One probable reason for the noise, says the Japanese carmaker, is insufficient torque at the No. 2 retaining bolt for the lower control arm(s). Retightening the bolt at both control arms to a revised torque of 110 ft.-lbs. should eliminate the ruckus.

Once you get the vehicle in the air, look for the presence of orange paint on the head of the bolt. If you don't see the paint mark, go ahead and retighten the bolt to the revised torque setting noted above. If you *do* see an orange mark, it means the bolt is a "one and done" design—in other words, it can be tightened only once. If that's the case, remove and toss the bolt and install a new-design fastener (Part No. 90119-14151), tightening it to the new torque setting indicated. To complete the fix, repeat the procedure at the other control arm, lower the vehicle and go on a road test to confirm that the clunking noise has been eliminated.

Cadillac

Fuel gauge troubles. Drivers of 2004-06 SRX, 2004-07 CTS and 2005-07 STS models with the 2.8 or 3.6L engine may come into your shop with a complaint that their fuel gauge reads empty even though there's plenty of gasoline remaining in the tank. Cadillac says the inaccurate gauge reading may be accompanied by a "Fuel Level Low" message on

the driver information center and, in some cases, an illuminated MIL with DTC P2066 in PCM memory.

One likely cause of the troubles is the PCM incorrectly relaying to the trip computer the actual amount of fuel being used, especially during short trips with frequent key cycles between fill-ups. Reprogramming the module with updated software is the only sure-fire remedy. You'll find the new calibration files at TIS2WEB on the internet.

Toyota

MIL illuminated, hybrid battery pack DTC(s) logged. A 2012-14 Prius V hybrid model may come into your shop one day with the MIL on and hybrid battery pack DTC P0A80 and/or P0A7F logged in the PCM.

According to Toyota, either trouble code means the battery pack has deteriorated, and in this case the deterioration is due to an overheating condition caused by dust or road debris clogging up the battery's cooling fan housing. Cleaning out the housing with compressed air or a shop vac, replacing the battery pack (Part No. G9510-76010) and installing a new intake filter for the housing (Part No. G92DH-47040) should prevent a recurrence of the condition.

Chrysler

Howling or groaning noise, flashing ESP light. Owners of 2008-09 Dodge Challengers, plus 2009 Dodge Charger and Chrysler 300 and 300C models—all with the 3.5, 5.7 or 6.1L engine—may complain of a howling or growling sound from the electronic stability program (ESP) pump when driving in a straight line following an aggressive low-speed turning event. Furthermore, the ESP light on SRT vehicles may flash repeatedly even though the ESP system has been switched off by the driver.

According to Chrysler, all of these problems are limited to vehicles without adaptive cruise control systems and built before 10/10/08, and are due to software anomalies in the ABS module. Reprogramming the module with updated software is the only reliable fix.

To do the flash, you'll need a

StarSCAN scanner operating at software release 9.03 or higher. The actual calibration files must be retrieved off Chrysler's website.

Honda

MIL on, cooling system DTC logged. Some 2008-10 Odyssey minivans may come into your shop with the MIL on and DTC P0128 (cooling system malfunction) stored in computer memory. If the cooling system checks out fine and there are no symptoms related to the code, it's probably bogus, says Honda, and caused by the PCM misinterpreting key input signals from several sensors during engine warm-up. Reprogramming the module with updated software is the only viable solution.

To do the flash, you'll need an HDS operating at software version 2.024.011 or later. Here are the application specifics for the new calibrations:

Program ID	Program Part No.
2008 LX, EX:	
GLA930	37805-RGL-A93
2008 EX-L, Touring:	
GWA960	37805-RGW-A96
2009-10 LX, EX:	
GLA020	37805-RGL-A02
2009-10 EX-L, Touring:	
GWA060	37805-RGW-A06

Chrysler

Noise from brake pedal. Owners of 2004 Pacifica models may come in with a complaint of a creak or squeak from the brake pedal under light to moderate braking.

According to Chrysler, the problem is limited to vehicles built on or before 3/28/03 and is most likely due to abnormal contact between the brake pedal return spring coils. Lubing the spring with multipurpose grease (Part No. 05083149AA or an equivalent) should eliminate the annoyance. For best results, press and release the brake pedal five to ten times to allow the grease to work its way into the coils.

GM

A/C system blows warm air. The owner of a 2008-10 Chevy Cobalt, Pontiac G5 or 2008-11 Chevy HHR

may come into your shop with a complaint that his a/c system blows nothing but warm air. On initial investigation, you might find that the a/c clutch isn't engaging when the switch on the control head is activated. That explains the warm air complaint, but what's causing the problem?

To find out, hook up your scan tool, check for DTCs related to the a/c system and repair as necessary. If no DTCs pop up on the scanner display, go into the datastream and look at the PIDs for AC Request, AC Relay Command and AC Pressure Sensor. If you see "No" next to the first two PIDs and zero pressure from the pressure sensor, you're likely dealing with a BCM that was improperly set up during a previous repair, says GM.

To right the ship, try enabling the AC option in the BCM with your scanner. If the option isn't listed on the display, the module is trash and needs to be replaced. Once the new BCM is installed, take your time during module setup to ensure that all the correct vehicle options are selected. If you're careless and miss a few, you could be introducing the same problem you're trying to rectify!

Ford/Ford Truck

Multiple driveability problems, DTC(s) logged. Some 2012-14 Ford Edges and Explorers, as well as 2013-14 Ford Taurus and Lincoln MKT models (all with the 2.0L direct-injected turbocharged engine) may produce a host of driveability issues. Among the engine complaints you might hear are that it's difficult to start or won't start at all, is down on power, hesitates on acceleration and/or idles poorly.

Ford says the driveability woes will likely be accompanied by an illuminated MIL, with DTCs P0106, P0128 and/or P0236 logged in the PCM. One likely cause of all of these symptoms is a bad signal return splice.

Start the fix by hooking up your scanner and checking for trouble

codes. If P0128 is the only code logged, check and, if necessary, adjust the coolant level. Next, grab a wiring schematic and locate the signal return splice (S176 on Edges and Explorers, S113 on Tauruses and S112 on MKTs). Once you find it, cut out the bad wiring and replace it with 5 in. of 18-gauge wire and a couple of crimps from a terminal kit. To complete the repair, backfill the crimps with solder, seal the new splice with heat-shrink tubing, clear the code(s), start the engine and verify that the driveability issues have been resolved.

Lexus

Noise from brake booster. Some 2004-10 RX 330/350 SUVs may produce an irritating buzz or rattle from just behind the left portion of the instrument panel. One likely cause of the noise, says Lexus, is a defective brake booster check valve. Replacing it with an improved design unit should eliminate further headaches.

To make an accurate diagnosis, take the truck on the road and lightly accelerate, then quickly take your foot off the gas pedal. You may also be able to duplicate the condition in the shop by depressing, then releasing the brake pedal with the transmission in Park. If you hear the rattle or buzz in either instance, that verifies that the original check valve is defective and the new-design valve needs to be installed. Order Part No. 44730-20080 for the valve with a straight nipple, 44730-14050 for the valve with a 90° nipple.

Toyota

MIL on, misfire DTC(s) logged. Some 2003-04 Celica models with the 1ZZ-FE engine and manual gearbox built before VIN JTDDR3#T#40176236 may illuminate the MIL and log random misfire DTC P0300 and/or single-cylinder misfire DTCs P0301 through P0304 in PCM memory.

If your scan tool reveals nothing out of the ordinary and there are no driveability symptoms, the code(s) are probably bogus, says Toyota, and

due to fuzzy logic in the PCM. Replacing the module with a new unit with revised software (Part No. 89661-2G382) is the only reliable fix.

Chrysler

MIL illuminated on dash, MAP sensor DTC stored. Some 2012 Dodge Caravan and Chrysler Town & Country minivans with the 3.6L engine built before 6/25/12 may turn on the MIL and log DTC P0108 (MAP Sensor Circuit High) in the PCM, as either a current or history code.

According to Chrysler, if there are no other DTCs stored and no driveability symptoms associated with the MAP sensor code, it's likely bogus and caused by software anomalies in the PCM. Reprogramming the module with updated software is the only way to permanently fix the problem. To do the flash, you'll need a wiTECH scanner operating at software release 13.01 or higher.

Note: Two different software packages are available for these vehicles, depending on various option codes and accessories. Check with a dealer to determine the correct calibration files for the specific vehicle in your service bay.

Dodge Truck/Jeep

Inoperative a/c system. The owner of a 2012-13 Dodge Durango or Jeep Grand Cherokee with the remote start system and dual-zone or three-zone ATC system may come into your shop one day with a complaint that his a/c system won't engage when the switch on the control head is activated.

When he does, start the vehicle in the conventional manner (using the start button) and try to turn on the a/c system. If the compressor clutch engages, shut the engine down, then restart the vehicle, only this time using the remote start feature on the key fob. If the a/c system now refuses to work, you're dealing with software anomalies in the ATC module. According to the folks at Dodge/Jeep, the problem is limited to vehicles built between 1/16/12 and 8/8/12 and can be rectified only by reprogram-

continued on page 50

Service Slants

ming the ATC module with updated software. To do the flash, you'll need a wiTECH scanner operating at software release 13.01 or higher.

Lexus

Clicking noise from brakes. Some 2007 LS 460 and LS 460L models may emit an irritating clicking noise from the front or rear when applying the brake pedal while traveling slowly in Reverse, or while changing direction from Drive to Reverse. Lexus attributes the noise to the design of the disc brake pad backing plates, which causes momentary sticking of the pads in the caliper supports as the wheels rotate counterclockwise. The fix depends on the option package and wheel size of the vehicle in your stall.

For LS 460 and LS 460L models with standard 18-in. wheels, replace the front and rear brake pads with updated designs (Part Nos. 04465-50260 and 04466-50130, respectively), using a liberal application of a newly formulated disc brake grease (Part No. 08887-80609). LS 460L models with the Touring Package and 19-in. wheels already have the updated brake pads installed. For these vehicles, just remove the pads and apply the new brake grease to the backing plates.

Toyota

Oil leakage from underneath engine. Owners of 2007 Japanese-built Camry models (VIN beginning with the letter "J") with the 2GR-FE V6 engine may come into your shop with a complaint of a slight but persistent oil leak from underneath the engine. One likely source of the leakage, says Toyota, is the interface where the bank 1 cylinder head, the engine block and the timing cover meet.

To make an accurate diagnosis, Toyota recommends adding some fluorescent dye to the crankcase and letting it circulate. If the dye confirms that the leakage is coming from the cylinder head, block and timing cover interface, reseal the cover, then add additional dye to verify that the leak has been eliminated.

Ford Truck


Rear suspension noise, vibration. Some owners of 2005-06 Ford Expeditions and Lincoln Navigators may complain of a clunking, grinding or thumping noise from the rear suspension on acceleration, when the transmission shifts or when the vehicle is moved from Drive to Reverse or Reverse to Drive. Ford says the noise is most prevalent on vehicles built before 6/13/05, may be accompanied by a vibration and *could* be due to loose torque arm-to-rear axle housing attaching bolts.

To make a definitive diagnosis, turn off the air suspension switch (if the vehicle is so equipped), put the truck in the air and check the torque arm bolts. If they're tight, this information doesn't apply; continue troubleshooting until the cause of the noise and/or vibration issue(s) is revealed.

If the torque arm bolts *are* loose, support the rear axle with stands, then remove the bolts and the torque arms. Next, inspect the arms to see if they're damaged or bent. If either arm is damaged, replace it with a revised unit (Part No. 5L1Z-4612-AA). If the torque arms are okay, reinstall them using four new retaining bolts (Part No. 5L1Z-4382-A). To complete the repair, tighten the bolts to 150 ft.-lbs., lower the vehicle and go on a road test to verify that the noise has been eliminated.

Dodge Truck/Jeep

MIL illuminated, MAP sensor DTC logged in PCM. Some 2012 Dodge Durango and Jeep Grand Cherokee SUVs with the 3.6L engine may turn on the MIL and log DTC P0108 (Manifold Absolute Pressure Sensor Circuit High) in computer memory.

The Dodge/Jeep service engineers say if there are no other codes stored and there are no driveability symptoms associated with the P0108, it's likely bogus and the direct result of software gremlins in the PCM. Reprogramming the module with updated calibration files is the proper fix. To do the flash, you'll need a wiTECH scanner operating at software release 13.01 or higher. 

Eye On Electronics

continued from page 19

ping and then close the deck lid. With the seal out of the way, he's able to see if the trunk light stays on even though the lid is closed. He also suggested simply pulling those bulbs and waiting to see if the problem goes away.

Jaguar service bulletins suggest looking for pinched seat motor wiring that might intermittently cause a drain based on seat position. Fixes to these intermittent problems are published in service bulletins and by information companies like Identifix.

Another tech suggested using a laser pointer-type infrared temperature-measuring device. These are relatively inexpensive measuring devices that let you measure the temperature of whatever you point at. The idea here is to measure the temperature of relays and other assemblies. If the device is supposed to be off—and not drawing current—it should be at the same temperature as the rest of the vehicle. If it's drawing current, it will be warmer than the surrounding components. He said he has used an infrared temperature-measuring device to find relays that were hung up or in the On condition when they weren't supposed to be.

There are a couple of good lessons to be learned from all of this. The first is that to truly tackle a key-off drain problem, you need information. You need to know from the owner what might have been replaced since the vehicle was delivered. You need to know how long the drain takes and if it happens consistently. You also need to know about the owner's driving habits.

From the manuals you need to know and understand how the system is supposed to work. Normal key-off current draws differ from vehicle to vehicle, and you need to know what's right for the one in your service bay. Without this kind of help, you might never know real important information—like there's a second battery hidden in the trunk!

The last thing is to not forget to use your creativity. You can learn on your own, or maybe from your fellow techs, ideas like using a scanner to look for processors that are supposed to be off but are not. If you have ideas you're willing to share, let us know and we'll pass them on for you. 