


FIG. 17-08 VACUUM PIPING

(0405-)2AZFE..ANT10



Mine was split right here where it goes over the tubing. I just cut the end off and re-installed.

PROB. DATE	MODELS	DESCRIPTION	R/P	PART NUMBER	REV. REF	
					Q T	F T
N 0405-	2AZFE..ANT10	1 23826 HOSE, FUEL VAPOR FEED, NO. 1		23826-2820-	1	
S 0405-	2AZFE..ANT10	1 23826A CLIP (FOR FUEL VAPOR FEED HOSE, NO.1)		96132-51100-	2	
S 0405-	2AZFE..ANT10	1 23827A HOSE, FUEL VAPOR FEED, NO.2		25827-28250-	1	
S 0405-	2AZFE..ANT10	1 23827B CLIP (FOR FUEL VAPOR FEED HOSE, NO.2)		96132-41000-	1	
S 0405-	2AZFE..ANT10	NO.2		96132-51100-	1	
N 0405-	2AZFE..ANT10	1 23829 HOSE, FUEL VAPOR FEED, NO.3		23829 28100-	1	
S 0405-	2AZFE..ANT10	1 23829B CLIP (FOR FUEL VAPOR FEED HOSE)		96132 51100	2	
N 0405	2AZFE..ANT10	1 25860 VALVE ASSY, VACUUM SWITCHING, NO.1		25860 28120	1	
S 0405	2AZFE..ANT10	1 25860A VALVE, VACUUM SWITCHING, NO.1		90910 12259	1	
S 0405	ANT10	1 77739 VALVE, EVAP SERVICE PORT		77739 35010	1	